

S29397

120W/LED/HID/5000K/100-277V/EX39 120 watt - LED HID Replacement; 5000K; Mogul extended base; 100-277 volts

Features

- High Lumen Omni-directional LED for Industrial / Commercial applications
- Replaces HID, CFL, and Incandescent
 Ballast by-pass Direct wire only 100V 277V
- UL approved for totally enclosed fixtures
 Damp location IP65 rated
- For outdoor & indoor use
- DLC Listed
- Base up or base down operation (high/low bay and post top)
- Emits no UV light / Contains no mercury (Hg)
- Built-in surge protection 5KV
- 5 year limited warranty
- Classified under UL 1598C
- · Safety chain included

Additional Technical Specifications

- Power Factor >0.9
- Operating temperature range -20°C to 65°C
- Operating Frequency 50-60Hz
- Working Voltage AC90-305V
- Built in surge protection

Minimum Compartment Size							
Length	Width	Depth					
17.3 inch	9.25 inch	9.25 inch					

Optional accessory: In-line surge protector 80-929



220	207
OZE	າວອາ

Item Number	Product Line	UPC	Input Voltage	' Watte		Incandescent Equivalent	Fluorescent Equivalent	
S29397	Hi-Pro	045923293979	100 - 277	120	50/60Hz	750W	200W	

HID	Door	ANSI	Lamp Cada	Dimmable/Non-	Finish	MOL In	MOD In
Equivalent	Base	Base	Lamp Code	Dimmable		Inches	Inches

600W	Mogul Extended	EX39	120W/LED/HID/5000K/100- 277V/EX39				Non-Di	mmable	White	10-3/8"	5.87"	
Initial Lumen	Average Rates Hours	ted	Kelvin Temp	Color	CRI	Bear	n Spread Deg	Oper	ating Tem	perature	Pack	
16000	50000		5000	Natural Ligh	t 80+		300	-20C (-4F) to a maxi +65C (+149F			4	
Package Type	CEC Status		DLC ID		RoHS Complia		UL Classi	fication	Warranty	Thei Manag	mal jement	
Вох	Lawful for sale in California		9GUMYDE PWJ4LI4A <u>earch</u>);	Yes		cULus - Wet Location Rated		5 Year Limited		More Details About	



National Toll-Free: 800.43.SATCO (800.437.2826) www.satco.com

Distribution Centers: New York, Florida, Texas, Washington, California, Puerto Rico Corporate Offices: 110 Heartland Blvd., Brentwood, NY 11717 800.437.2826 631.243.2022 Fax 631.243.2027



©2012, Satco Products, Inc. Not responsible for typographical errors. 06/12 S1051